REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Re-Inspection	**Date:**	7/20/2018	**Time:**	1:09 PM
Name of School Corporation:	OAK HILL UNITED SCHOOL CORP.			**Corp ID:**	525625
Address of School Corporation:	PO Box 550				
City:	Converse	**Zip:**	46919	**County Number:**	52
VIN:	4DRBUSKN49B095306	**License Number:**	30875	**Bus Number:**	16
Make of Body:	IC Corporation **Year:** 2008	**Make of Chassis:**	IC Corporation	**Year:**	2009
Bus Type:	C	**Mileage:**	135938		
Inspection Status:	O	**Inspected By:**	Randy McPike	**PE:**	7018

Violations - Rejected

Inspection Code	Description
35-1-1	A heater motor is not operating properly

Violations - Out of Service

Inspection Code	Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.