

## REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual	Date:	7/24/2018	Time:	8:46 AM		
Name of School Corporation:	NORTHEAST SCHOOL CORPORATION			Corp ID:	777645		
Address of School Corporation:	PO Box 493						
City:	Hymera	Zip:	47855	County Number:	77		
VIN:	4DRBWAAR38A503274		License Number:	11227	Bus Number:	3	
Make of Body:	IC Corporation	Year:	2007	Make of Chassis:	IC Corporation	Year:	2008
Bus Type:	D		Mileage:	115642			
Inspection Status:	R	Inspected By:	Byron Goodman	PE:	7008		

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
57-1-5	Step-well light is missing or inoperative

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
------------------------	--------------------

### Bus Type Description

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.