REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual	**Date:**	7/25/2018	**Time:**	12:45 PM
Name of School Corporation:	NORTH DAVIESS CO. COMM. SCHOOL			**Corp ID:**	141375
Address of School Corporation:	5494 E SR 58				
City:	Elnora	**Zip:**	47529	**County Number:**	14
VIN:	4UZAAXBV62CJ97773	**License Number:**	D784792	**Bus Number:**	16
Make of Body:	Freightliner **Year:** 2001	**Make of Chassis:**	Freightliner	**Year:**	2002
Bus Type:	C	**Mileage:**	164826		
Inspection Status:	O	**Inspected By:**	Kelly Hammond	**PE:**	6682

Violations - Rejected

Inspection Code	Description
69-1-3	Wiper blades are torn, cracked, brittle or otherwise deteriorated

Violations - Out of Service

Inspection Code	Description
7-2-2	Any push-rod travel measures 1/4 inch or more beyond the readjustment limit, or if any two (2) brakes measure less than 1/4 inch beyond the readjustment limit
22-2-2	There is a significant leak from the engine or transmission onto the exhaust system which could potentially cause a fire

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.