REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual			**Date:**	7/31/2018	**Time:**	10:06 AM
Name of School Corporation:		BAUGO COMMUNITY SCHOOLS				**Corp ID:**	202260
Address of School Corporation:			29125 CR 22 W				
City:	Elkhart		**Zip:**	46517		**County Number:**	20
VIN:	4DRBUAAP09B670952			**License Number:**	B969B	**Bus Number:**	4
Make of Body:	IC Corporation	**Year:**	2007	**Make of Chassis:**	IC Corporation	**Year:**	2009
Bus Type:	C			**Mileage:**	64734		
Inspection Status:	R		**Inspected By:**	Wes Rowlader		**PE:**	7427

Violations - Rejected

Inspection Code	Description
46-1-5	Upholstery or padding is ripped, torn, or improperly repaired
46-1-2	Any seat back or bottom is loose

Violations - Out of Service

Inspection Code	Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.