

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b>	Registration	<b>Date:</b>	8/3/2018	<b>Time:</b>	9:09 AM
<b>Name of School Corporation:</b>	LUTHERAN HIGH SCHOOL	<b>Corp ID:</b>	49C270		
<b>Address of School Corporation:</b>	5555 S Arlington Ave				
<b>City:</b>	Indianapolis	<b>Zip:</b>	46237	<b>County Number:</b>	49
<b>VIN:</b>	1GBHG31R011139445	<b>License Number:</b>	B776aa	<b>Bus Number:</b>	4
<b>Make of Body:</b>	Thomas Built Buses, Inc.	<b>Year:</b>	2001	<b>Make of Chassis:</b>	Chevrolet
<b>Bus Type:</b>	C	<b>Year:</b>	2001	<b>Mileage:</b>	93677
<b>Inspection Status:</b>	O	<b>Inspected By:</b>	Jeff Kastenschmidt	<b>PE:</b>	5805

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
66-1-1	Required warning devices are not present
46-1-5	Upholstery or padding is ripped, torn, or improperly repaired
51-1-1	Any door seals are missing, damaged, or torn
22-1-5	See Notes: Any defect inspector deems a violation not listed

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
63-2-3	Any tire is flat
48-2-2	There is a severe leak from any point

### Bus Type Description

**Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.**