

## REPORT OF SCHOOL BUS INSPECTION

|                                |                              |               |                 |                  |                |       |      |
|--------------------------------|------------------------------|---------------|-----------------|------------------|----------------|-------|------|
| Type of Inspection:            | Annual                       | Date:         | 8/6/2018        | Time:            | 8:45 AM        |       |      |
| Name of School Corporation:    | CENTRAL NINE VOC-TECH SCHOOL |               |                 | Corp ID:         | 414265         |       |      |
| Address of School Corporation: | 1999 US 31 S                 |               |                 |                  |                |       |      |
| City:                          | Greenwood                    | Zip:          | 46142           | County Number:   | 41             |       |      |
| VIN:                           | 4DRBUSKN57B673963            |               | License Number: | 32963            | Bus Number:    | 9     |      |
| Make of Body:                  | IC Corporation               | Year:         | 2010            | Make of Chassis: | IC Corporation | Year: | 2010 |
| Bus Type:                      | C                            |               |                 | Mileage:         | 13262          |       |      |
| Inspection Status:             | O                            | Inspected By: | John Pang       | PE:              | 6196           |       |      |

### Violations - Rejected

| <u>Inspection Code</u> | <u>Description</u>   |
|------------------------|--|
| 62-1-2                 | One (1) taillight or one (1) brake light does not function |

### Violations - Out of Service

| <u>Inspection Code</u> | <u>Description</u>  |
|------------------------|---|
| 7-2-1                  | There is no brake certification form the certification is expired or is not signed within the six-month requirement |

### Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.