

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Post-Crash Inspection	Date:	8/6/2018	Time:	11:19 AM
Name of School Corporation:	M.S.D. PERRY TOWNSHIP	Corp ID:	495340		
Address of School Corporation:	1319 W Edgewood Ave				
City:	Indianapolis	Zip:	46217	County Number:	49
VIN:	1BABNCPA1HF329688	License Number:	11834	Bus Number:	1294
Make of Body:	Blue Bird Corporation	Year:	2016	Make of Chassis:	Blue Bird Corporation
Bus Type:	D	Mileage:	22698		
Inspection Status:	O	Inspected By:	John Pang	PE:	6196

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
20-1-10	See Notes: Any defect inspector deems a violation not listed
62-1-2	One (1) taillight or one (1) brake light does not function
11-1-2	The front or rear bumper is not properly attached, missing, torn, loose, or altered.
32-1-5	See Notes: Any defect inspector deems a violation not listed

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
20-2-2	Door glass is missing
24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).

Bus Type Description

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.