REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual	**Date:**	8/16/2018	**Time:**	9:14 AM
Name of School Corporation:	BROWN"S BUS TRANSPORTION			**Corp ID:**	82008Z
Address of School Corporation:	2120 Culverson				
City:	Evansville	**Zip:**	47714	**County Number:**	82
VIN:	4UZABRDT58CZ11034	**License Number:**	B722N	**Bus Number:**	M7
Make of Body:	Freightliner **Year:** 2007	**Make of Chassis:**	Freightliner	**Year:**	2007
Bus Type:	C	**Mileage:**	83540		
Inspection Status:	O	**Inspected By:**	Bradley MIller	**PE:**	7809

Violations - Rejected

Inspection Code	Description
64-1-4	Any front turn signal does not function properly

Violations - Out of Service

Inspection Code	Description
64-2-1	Any rear turn signal does not function properly
65-2-1	Warning lights fail to operate correctly

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.