REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual		**Date:**	8/22/2018 **Time:**	10:35 AM
Name of School Corporation:	ILLIANA CHRISTIAN HIGH SCHOOL			**Corp ID:**	45018Z
Address of School Corporation:	10920 CALUMET				
City:	DYER	**Zip:**	46311	**County Number:**	45
VIN:	1GBJG31U861168057		**License Number:**	M196441 **Bus Number:**	441
Make of Body:	Mid Bus, Inc. **Year:**	2006	**Make of Chassis:**	Chevrolet **Year:**	2006
Bus Type:	A2		**Mileage:**	75980	
Inspection Status:	O	**Inspected By:**	Nathan Sherer	**PE:**	7029

Violations - Rejected

Inspection Code	Description
28-1-4	The first aid kit is not complete: 3 packs of 16 1x3 adhesive strips, 1 scissor (4” min), 2 40”x40”x56” triangular bandages, 6 3”x3” gauze pads, 4 2”x4.1 yard rolls of gauze, 3 oval eye pads, 1 1”x5 yard of adhesive tape, 1 label instruction.
43-1-8	Any required lettering is missing or faded.
29-1-5	Prohibited area sign is missing or obscured

Violations - Out of Service

Inspection Code	Description
70-2-4	Audible warning device, when required, is not working properly. Buzzers are required after 5-2-94
50-2-1	There is no seat belt cutter in the vehicle

Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

1. **Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.**
2. **Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.**