

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Annual Date: 8/22/2018 Time: 10:06 AM
Name of School Corporation: MTC INTRANS Corp ID: 240005
Address of School Corporation: 6910 N. Main St
City: Granger Zip: 46530 County Number: 71
VIN: 1GBHG31R311107671 License Number: B752AC Bus Number: 3
Make of Body: Chevrolet Year: 2000 Make of Chassis: Chevrolet Year: 2001
Bus Type: A1 Mileage: 449389
Inspection Status: O Inspected By: Travis Harrold PE: 8022

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
30-1-2	There are weak areas due to deterioration
30-1-1	There are any holes in the floor
57-1-2	Step-well area is weakened
41-1-2	Any interior protrusions have sharp edges or corners
24-1-1	The bus body has rust or rusted through areas which may weaken the body
29-1-2	Floor covering is missing, cut, loose, buckled, bulging, or not secure
29-1-3	There are holes in the floor

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).

Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.
2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.