REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Spot Checks			Date:	8/28/2018	Time:	11:48 AM
Name of School Corporation: Address of School Corporation:		NOR	NORTH LAWRENCE COMM. SCHOOLS 595 Stars Blvd			Corp ID:	475075
City:	Bedford		Zip:	47421		County	47
ony.	Dealora		с ір.			Number:	-1
VIN:	4UZABRDT3ACAM02	07		License Number:	32164	Bus Number:	A39
Make of Body:	Thomas Built Buses, Inc.	Year:	2008	Make of Chassis:	Freightliner	Year:	2010
Bus Type:	С			Mileage:	Unknown		
Inspection Status:	A		Inspected By:	Travis Coryea		PE:	5892

Violations - Rejected

Inspection Code Description

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.