

## REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Post-Crash Inspection	Date:	8/31/2018	Time:	9:54 AM		
Name of School Corporation:	NORTH NEWTON SCHOOL CORP.		Corp ID:	565945			
Address of School Corporation:	PO Box 8						
City:	Morocco	Zip:	47963	County Number:	56		
VIN:	4DRBUAAP3CB655336		License Number:	2693	Bus Number:	24	
Make of Body:	IC Corporation	Year:	2012	Make of Chassis:	IC Corporation	Year:	2012
Bus Type:	C	Mileage:	76553				
Inspection Status:	O	Inspected By:	Tim Grayson	PE:	7558		

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
24-1-2	The bus body has loose, damaged or improperly aligned body parts. These would include rivets, bolts, and body panels and/or rub rails
67-1-2	Rims are bent or loose

### Violations - Out of Service

#### Inspection Code Description

#### Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.