REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Re-Inspection	**Date:**	9/5/2018	**Time:**	9:49 AM
Name of School Corporation:	NETTLE CREEK SCHOOL CORP.			**Corp ID:**	898305
Address of School Corporation:	795 Baker Rd				
City:	Hagerstown	**Zip:**	47346	**County Number:**	89
VIN:	4DRBRABP54B969104	**License Number:**	19897	**Bus Number:**	2
Make of Body:	AmTran **Year:** 2003	**Make of Chassis:**	AmTran	**Year:**	2003
Bus Type:	C	**Mileage:**	144573		
Inspection Status:	O	**Inspected By:**	Jeremy Mason	**PE:**	8139

Violations - Rejected

Inspection Code	Description
35-1-1	A heater motor is not operating properly
2-1-1	Required back-up lights do not function.
46-1-5	Upholstery or padding is ripped, torn, or improperly repaired

Violations - Out of Service

Inspection Code	Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.