

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b>	Semi-Annual	<b>Date:</b>	9/12/2018	<b>Time:</b>	9:00 AM
<b>Name of School Corporation:</b>	NORTHEAST DUBOIS CO. SCH. CORP			<b>Corp ID:</b>	192040
<b>Address of School Corporation:</b>	5379 E Main St				
<b>City:</b>	Dubois	<b>Zip:</b>	47527	<b>County Number:</b>	19
<b>VIN:</b>	4DRBUAAN25B985616	<b>License Number:</b>	B398K	<b>Bus Number:</b>	15
<b>Make of Body:</b>	IC Corporation	<b>Year:</b>	2004	<b>Make of Chassis:</b>	IC Corporation
<b>Year:</b>				<b>Year:</b>	2005
<b>Bus Type:</b>	C	<b>Mileage:</b>	129852		
<b>Inspection Status:</b>	R	<b>Inspected By:</b>	Kelly Hammond	<b>PE:</b>	6682

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
16-1-1	There are any leaks from the differential, pinion seal, or either rear wheel seal
50-1-2	The seat belt cutter is not secured
3-1-3	Any battery is loose in its mounting.

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
------------------------	--------------------

### Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.