

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Post-Crash Inspection	Date:	9/14/2018	Time:	9:23 AM
Name of School Corporation:	PERU COMMUNITY SCHOOLS	Corp ID:	525635		
Address of School Corporation:	35 W 3rd St				
City:	Peru	Zip:	46970	County Number:	52
VIN:	1GB6G5BGXF1102054	License Number:	031241	Bus Number:	Tiger3
Make of Body:	Thomas Built Buses, Inc.	Year:	2015	Make of Chassis:	Chevrolet
Bus Type:	A2	Mileage:	61809		
Inspection Status:	<input type="radio"/>	Inspected By:	Randy McPike	PE:	7018

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
60-1-1	Sun visor is missing, cracked or broken
11-1-2	The front or rear bumper is not properly attached, missing, torn, loose, or altered.

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
31-2-1	Frame is deteriorated, cracked, broken or severely bent

Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.
2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.