

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Annual	Date: 9/18/2018	Time: 9:58 AM
Name of School Corporation: SOUTH BEND COMM. SCHOOL CORP.	Corp ID: 717205	
Address of School Corporation: 3003 N Bendix Dr		
City: South Bend	Zip: 46601	County Number: 71
VIN: 4DRBUAAN78B493829	License Number: 31241	Bus Number: 209
Make of Body: IC Corporation	Year: 2006	Make of Chassis: IC Corporation
Year: 2008		
Bus Type: C	Mileage: 126738	
Inspection Status: O	Inspected By: Travis Harrold	PE: 8022

Violations - Rejected

Inspection Code Description

Violations - Out of Service

Inspection Code

Description

24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).
--------	---

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.