

## REPORT OF SCHOOL BUS INSPECTION

**Type of Inspection:** Post-Crash Inspection      **Date:** 9/19/2018      **Time:** 3:22 PM  
**Name of School Corporation:** SOUTH DEARBORN COMM. SCH. CORP      **Corp ID:** 151600  
**Address of School Corporation:** 6109 Squire Place  
**City:** Aurora      **Zip:** 47001      **County Number:** 15  
**VIN:** 1BAKF2PH58F250485      **License Number:** b935f      **Bus Number:** 22  
**Make of Body:** Blue Bird Corporation      **Year:** 2007      **Make of Chassis:** Blue Bird Corporation      **Year:** 2008  
**Bus Type:** C      **Mileage:** 115142  
**Inspection Status:** O      **Inspected By:** Chris Clark      **PE:** 6665

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
25-1-1	Mirror or mirror backs that are loose or improperly mounted
22-1-1	A dripping oil or fluid leak
33-1-1	The grill has any exposed edges that may cause injury
24-1-2	The bus body has loose, damaged or improperly aligned body parts. These would include rivets, bolts, and body panels and/or rub rails

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
25-2-1	Mountings are broken or bent badly enough to inhibit proper adjustment
8-2-5	There is brake fluid leaking at any point

### Bus Type Description

**Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.**