

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Post-Crash Inspection	Date: 9/26/2018	Time: 2:50 PM
Name of School Corporation: SOUTH HARRISON COMM. SCH. CORP	Corp ID: 313190	
Address of School Corporation: 315 S Harrison Dr		
City: Corydon	Zip: 47112	County Number: 31
VIN: 4DRBRABN44B960716	License Number: B671F	Bus Number: 11
Make of Body: IC Corporation	Year: 2004	Make of Chassis: IC Corporation
Year: 2004	Mileage: 67855	Year: 2004
Bus Type: C		
Inspection Status: O	Inspected By: Troy Boyd	PE: 5171

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
34-1-1	Any headlight is inoperative
33-1-1	The grill has any exposed edges that may cause injury
13-1-1	Any clearance light is missing, cracked, faded, wrong color, or inoperative
11-1-2	The front or rear bumper is not properly attached, missing, torn, loose, or altered.
44-1-1	Any marker light or lens is missing, cracked, faded, wrong color, or inoperative
64-1-4	Any front turn signal does not function properly
64-1-2	A lens is cracked, missing or wrong color
70-1-4	There is any cracked glass to the immediate right or left of the driver
70-1-3	There are any breaks, nicks or chips larger than 3/4 inch in diameter in the area covered by the wipers on the drivers' side
70-1-2	There are intersecting cracks in the windshield area covered by the wipers
51-1-1	Any door seals are missing, damaged, or torn
24-1-2	The bus body has loose, damaged or improperly aligned body parts. These would include rivets, bolts, and body panels and/or rub rails
23-1-3	Any exhaust leak can be felt with the bare hand six (6) inches from the leak in any direction (with the engine idling and the system unrestricted).
41-1-2	Any interior protrusions have sharp edges or corners

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
25-2-1	Mountings are broken or bent badly enough to inhibit proper adjustment
25-2-2	Reflective glass is cracked, broken, or missing
39-2-1	Inner fenders are loose from body or mounting brackets
70-2-1	Any glass or glazing is broken through or missing

24-2-1 There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.