# REPORT OF SCHOOL BUS INSPECTION

| | | | | | |
|---|---|---|---|---|---|
| **Type of Inspection:** | Annual | **Date:** | 9/27/2018 | **Time:** | 9:34 AM |
| **Name of School Corporation:** | SCHOOL CITY OF MISHAWAKA | | | **Corp ID:** | 717200 |
| **Address of School Corporation:** | 1402 S Main St | | | | |
| **City:** | Mishawaka | **Zip:** | 46544 | **County Number:** | 71 |
| **VIN:** | 1GBJB31K781207058 | **License Number:** | 79250 | **Bus Number:** | 2 |
| **Make of Body:** | Chevrolet **Year:** 2008 | **Make of Chassis:** | Chevrolet | **Year:** | 2008 |
| **Bus Type:** | | **Mileage:** | 159883 | | |
| **Inspection Status:** | O | **Inspected By:** | Travis Harrold | **PE:** | 8022 |

**Violations - Rejected**

| Inspection Code | Description |
|---|---|
| 63-1-3 | Any front tire has less than 4/32 inch tread depth when measured in any two adjacent major grooves |
| 63-1-4 | Any rear tire has less than 2/32 inch tread depth when measured in any two adjacent major grooves |

**Violations - Out of Service**

| Inspection Code | Description |
|---|---|

**Bus Type Description**