

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b> Annual	<b>Date:</b> 9/27/2018	<b>Time:</b> 9:34 AM
<b>Name of School Corporation:</b> SCHOOL CITY OF MISHAWAKA	<b>Corp ID:</b> 717200	
<b>Address of School Corporation:</b> 1402 S Main St		
<b>City:</b> Mishawaka	<b>Zip:</b> 46544	<b>County Number:</b> 71
<b>VIN:</b> 1GBJB31K781207058	<b>License Number:</b> 79250	<b>Bus Number:</b> 2
<b>Make of Body:</b> Chevrolet	<b>Year:</b> 2008	<b>Make of Chassis:</b> Chevrolet
<b>Bus Type:</b>	<b>Mileage:</b> 159883	<b>Year:</b> 2008
<b>Inspection Status:</b> O	<b>Inspected By:</b> Travis Harrold	<b>PE:</b> 8022

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
63-1-3	Any front tire has less than 4/32 inch tread depth when measured in any two adjacent major grooves
63-1-4	Any rear tire has less than 2/32 inch tread depth when measured in any two adjacent major grooves

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
------------------------	--------------------

<u>Bus Type</u>	<u>Description</u>
-----------------	--------------------