REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual	**Date:**	9/28/2018	**Time:**	2:16 PM
Name of School Corporation:	EAST GIBSON SCHOOL CORPORATION			**Corp ID:**	262725
Address of School Corporation:	941 S Franklin St				
City:	Oakland City	**Zip:**	47660	**County Number:**	26
VIN:	1GB6G3AG8A1165037	**License Number:**	2369	**Bus Number:**	22
Make of Body:	Star Trans **Year:** 2010	**Make of Chassis:**	Chevrolet	**Year:**	2010
Bus Type:		**Mileage:**	79290		
Inspection Status:	R	**Inspected By:**	Bradley MIller	**PE:**	7809

Violations - Rejected

Inspection Code	Description
62-1-1	Any lens is cracked, missing, faded or of the wrong color
70-1-10	If the emergency window instructions are illegible or missing. Must be within 6 inches of the release handle

Violations - Out of Service

Inspection Code	Description

Bus Type Description