

## REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Annual Date: 9/28/2018 Time: 2:16 PM  
Name of School Corporation: EAST GIBSON SCHOOL CORPORATION Corp ID: 262725  
Address of School Corporation: 941 S Franklin St  
City: Oakland City Zip: 47660 County Number: 26  
VIN: 1GB6G3AG8A1165037 License Number: 2369 Bus Number: 22  
Make of Body: Star Trans Year: 2010 Make of Chassis: Chevrolet Year: 2010  
Bus Type: Mileage: 79290  
Inspection Status: R Inspected By: Bradley Miller PE: 7809

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
62-1-1	Any lens is cracked, missing, faded or of the wrong color
70-1-10	If the emergency window instructions are illegible or missing. Must be within 6 inches of the release handle

### Violations - Out of Service

### Inspection Code Description

### Bus Type Description