REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Annual Date: 9/28/2018 Time: 2:16 PM

Name of School Corporation: EAST GIBSON SCHOOL CORPORATION Corp ID: 262725

Address of School Corporation: 941 S Franklin St

City:Oakland CityZip:47660County Number:26VIN:1GB6G3AG8A1165037License Number:2369Bus Number:22Make of Body:Star Trans Year:2010Make of Chassis:ChevroletYear:2010

Bus Type: Mileage: 79290

Inspection Status: R Inspected By: Bradley Miller PE: 7809

Violations - Rejected

<u>Inspection</u> <u>Code</u>	<u>Description</u>
62-1-1	Any lens is cracked, missing, faded or of the wrong color
70-1-10	If the emergency window instructions are illegible or missing. Must be within 6 inches of the release handle

Violations - Out of Service

Inspection Code Description

Bus Type Description