

## REPORT OF SCHOOL BUS INSPECTION

|                                       |                              |                        |             |                         |           |
|---------------------------------------|------------------------------|------------------------|-------------|-------------------------|-----------|
| <b>Type of Inspection:</b>            | Registration                 | <b>Date:</b>           | 10/3/2018   | <b>Time:</b>            | 8:12 AM   |
| <b>Name of School Corporation:</b>    | RISING-SUN OHIO COUNTY COMM. |                        |             | <b>Corp ID:</b>         | 586080    |
| <b>Address of School Corporation:</b> | 110 Henrietta St             |                        |             |                         |           |
| <b>City:</b>                          | Rising Sun                   | <b>Zip:</b>            | 47040       | <b>County Number:</b>   | 58        |
| <b>VIN:</b>                           | 1HA3GRBG1JN007093            | <b>License Number:</b> |             | <b>Bus Number:</b>      | A6        |
| <b>Make of Body:</b>                  | Collins Bus Corporation      | <b>Year:</b>           | 2018        | <b>Make of Chassis:</b> | Chevrolet |
| <b>Bus Type:</b>                      |                              | <b>Mileage:</b>        | 785         | <b>Year:</b>            | 2018      |
| <b>Inspection Status:</b>             | A                            | <b>Inspected By:</b>   | Chris Clark | <b>PE:</b>              | 6665      |

### Violations - Rejected

| <u>Inspection Code</u> | <u>Description</u> |
|------------------------|--------------------|
|------------------------|--------------------|

### Violations - Out of Service

| <u>Inspection Code</u> | <u>Description</u> |
|------------------------|--------------------|
|------------------------|--------------------|

| <u>Bus Type</u> | <u>Description</u> |
|-----------------|--------------------|
|-----------------|--------------------|