

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Post-Crash Inspection **Date:** 10/3/2018 **Time:** 12:18 PM
Name of School Corporation: SPRINGS VALLEY COMM. SCH. CORP **Corp ID:** 596160
Address of School Corporation: 498 S Larry Bird Blvd
City: French Lick **Zip:** 47432 **County Number:** 59
VIN: 4DRBUAAP6AB137685 **License Number:** 716 **Bus Number:** 9
Make of Body: IC Corporation **Year:** 2009 **Make of Chassis:** IC Corporation **Year:** 2010
Bus Type: C **Mileage:** 62997
Inspection Status: O **Inspected By:** Kelly Hammond **PE:** 6682

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
24-1-2	The bus body has loose, damaged or improperly aligned body parts. These would include rivets, bolts, and body panels and/or rub rails

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.