

REPORT OF SCHOOL BUS INSPECTION

| | | | | | | | |
|--------------------------------|-------------------------|---------------|-----------------|------------------|----------------|-------|------|
| Type of Inspection: | Re-Inspection | Date: | 10/10/2018 | Time: | 2:03 PM | | |
| Name of School Corporation: | M.S.D. DECATUR TOWNSHIP | | | Corp ID: | 495300 | | |
| Address of School Corporation: | 5251 Kentucky Ave | | | | | | |
| City: | Indianapolis | Zip: | 46221 | County Number: | 49 | | |
| VIN: | 4DRBWAAR67A304623 | | License Number: | 21438 | Bus Number: | 75 | |
| Make of Body: | IC Corporation | Year: | 2005 | Make of Chassis: | IC Corporation | Year: | 2007 |
| Bus Type: | D | | | Mileage: | 92782 | | |
| Inspection Status: | O | Inspected By: | John Pang | PE: | 6196 | | |

Violations - Rejected

| <u>Inspection Code</u> | <u>Description</u> |
|------------------------|---|
| 34-1-1 | Any headlight is inoperative |
| 64-1-2 | A lens is cracked, missing or wrong color |
| 24-1-1 | The bus body has rust or rusted through areas which may weaken the body |
| 24-1-7 | See Notes: Any defect inspector deems a violation not listed |

Violations - Out of Service

| <u>Inspection Code</u> | <u>Description</u> |
|------------------------|--|
| 25-2-1 | Mountings are broken or bent badly enough to inhibit proper adjustment |

Bus Type Description

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.