

REPORT OF SCHOOL BUS INSPECTION

| | | | | | |
|---------------------------------------|--------------------------|------------------------|------------|-------------------------|--------------|
| Type of Inspection: | Semi-Annual | Date: | 10/19/2018 | Time: | 9:41 AM |
| Name of School Corporation: | ROCKCREEK COMM ACADEMY | Corp ID: | 109875 | | |
| Address of School Corporation: | 11525 HWY 31 N | | | | |
| City: | Sellersburg | Zip: | 47072 | County Number: | 10 |
| VIN: | 4UZAAXBV13CL71542 | License Number: | G533763 | Bus Number: | 1 |
| Make of Body: | Thomas Built Buses, Inc. | Year: | 2003 | Make of Chassis: | Freightliner |
| Year: | 2003 | Year: | 2003 | | |
| Bus Type: | C | Mileage: | 167511 | | |
| Inspection Status: | O | Inspected By: | Troy Boyd | PE: | 5171 |

Violations - Rejected

Inspection Code Description

Violations - Out of Service

Inspection Code

Description

| | |
|--------|---|
| 20-2-1 | Is no audible signal when the emergency door is open and ignition switch is on |
| 70-2-4 | Audible warning device, when required, is not working properly. Buzzers are required after 5-2-94 |

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.