

## REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Re-Inspection	Date:	10/22/2018	Time:	1:51 PM
Name of School Corporation:	EAST NOBLE SCHOOL CORPORATION			Corp ID:	576060
Address of School Corporation:	126 W Rush St				
City:	Kendallville	Zip:	46755	County Number:	57
VIN:	1T7Y84D20J1129496	License Number:	17907	Bus Number:	31
Make of Body:	Thomas Built Buses, Inc.	Year:	2017	Make of Chassis:	Thomas Built Buses, Inc.
Bus Type:	D			Mileage:	23114
Inspection Status:	O	Inspected By:	Wes Rowlader	PE:	7427

### **Violations - Rejected**

<u>Inspection Code</u>	<u>Description</u>
11-1-2	The front or rear bumper is not properly attached, missing, torn, loose, or altered.
7-1-3	Air leak at proper connection
59-1-7	Any optional rear stop arm device or school bus crossing arm criteria is not met

### **Violations - Out of Service**

<u>Inspection Code</u>	<u>Description</u>
31-2-1	Frame is deteriorated, cracked, broken or severely bent
24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).

### Bus Type Description

**Type D School Bus** – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.