

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Post-Crash Inspection	Date:	10/24/2018	Time:	10:46 AM		
Name of School Corporation:	JAY SCHOOL CORPORATION			Corp ID:	383945		
Address of School Corporation:	PO Box 1239						
City:	Portland	Zip:	47371	County Number:	38		
VIN:	4UZABRDU2DCFA4628	License Number:	4295	Bus Number:	6		
Make of Body:	Thomas Built Buses, Inc.	Year:	2012	Make of Chassis:	Thomas Built Buses, Inc.	Year:	2013
Bus Type:	C	Mileage:	184581				
Inspection Status:	O	Inspected By:	Jamie Hotchkiss	PE:	6458		

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
34-1-1	Any headlight is inoperative
36-1-1	The latch does not secure the hood tightly
11-1-7	See Notes: Any defect inspector deems a violation not listed

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
31-2-1	Frame is deteriorated, cracked, broken or severely bent
53-2-1	Any broken main leaf in a leaf spring
24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.