

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b>	Post-Crash Inspection	<b>Date:</b>	10/24/2018	<b>Time:</b>	10:46 AM
<b>Name of School Corporation:</b>	JAY SCHOOL CORPORATION	<b>Corp ID:</b>	383945		
<b>Address of School Corporation:</b>	PO Box 1239				
<b>City:</b>	Portland	<b>Zip:</b>	47371	<b>County Number:</b>	38
<b>VIN:</b>	4UZABRDU2DCFA4628	<b>License Number:</b>	4295	<b>Bus Number:</b>	6
<b>Make of Body:</b>	Thomas Built Buses, Inc.	<b>Year:</b>	2012	<b>Make of Chassis:</b>	Thomas Built Buses, Inc.
<b>Bus Type:</b>	C	<b>Mileage:</b>	184581		
<b>Inspection Status:</b>	O	<b>Inspected By:</b>	Jamie Hotchkiss	<b>PE:</b>	6458

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
34-1-1	Any headlight is inoperative
36-1-1	The latch does not secure the hood tightly
11-1-7	See Notes: Any defect inspector deems a violation not listed

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
31-2-1	Frame is deteriorated, cracked, broken or severely bent
53-2-1	Any broken main leaf in a leaf spring
24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)(Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district).

### Bus Type Description

**Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.**