REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Post-Crash Inspection		**Date:** 10/29/2018	**Time:**	1:12 PM
Name of School Corporation:	GREATER CLARK CO SCHLS			**Corp ID:**	101010
Address of School Corporation:	301 E 11th St				
City:	Jeffersonville	**Zip:**	47130	**County Number:**	10
VIN:	1HVBBABPX4H579454		**License Number:** B759J	**Bus Number:**	11C
Make of Body:	Blue Bird Corporation **Year:**	2003	**Make of Chassis:** IC Corporation	**Year:**	2004
Bus Type:	C		**Mileage:** 178346		
Inspection Status:	O	**Inspected By:**	Kelly Hammond	**PE:**	6682

Violations - Rejected

Inspection Code	Description
11-1-2	The front or rear bumper is not properly attached, missing, torn, loose, or altered.
34-1-1	Any headlight is inoperative
36-1-3	See Notes: Any defect inspector deems a violation not listed
50-1-2	The seat belt cutter is not secured
50-1-3	The seat belt cutter is contained in a compartment and not marked
82-1-2	See Notes: Any defect inspector deems a violation not listed

Violations - Out of Service

Inspection Code	Description
8-2-1	There is no brake certification, or the certification has expired or is not signed
70-2-4	Audible warning device, when required, is not working properly. Buzzers are required after 5-2-94

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.