

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Semi-Annual **Date:** 11/7/2018 **Time:** 8:16 AM
Name of School Corporation: CRAWFORD CO. COMM. SCHOOL CORP **Corp ID:** 131300
Address of School Corporation: 5808 E Administration Rd
City: Marengo **Zip:** 47140 **County Number:** 13
VIN: 4UZ6CFAA7XCA45441 **License Number:** B684E **Bus Number:** 10
Make of Body: Freightliner **Year:** 1999 **Make of Chassis:** Freightliner **Year:** 1999
Bus Type: C **Mileage:** 184418
Inspection Status: O **Inspected By:** Kelly Hammond **PE:** 6682

Violations - Rejected

Inspection Code Description

Violations - Out of Service

Inspection Code

Description

63-2-1 Tires are cut, weathered, cracked, have lumps, or breaks that expose the cord

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.