

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Semi-Annual	Date: 11/7/2018	Time: 10:48 AM
Name of School Corporation: CRAWFORD CO. COMM. SCHOOL CORP	Corp ID: 131300	
Address of School Corporation: 5808 E Administration Rd		
City: Marengo	Zip: 47140	County Number: 13
VIN: 1HVBBABP8XH208703	License Number: B616M	Bus Number: 1
Make of Body: IC Corporation	Year: 1999	Make of Chassis: AmTran
Year: 1999	Mileage: 148664	
Bus Type: C		
Inspection Status: R	Inspected By: Kelly Hammond	PE: 6682

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
2-1-1	Required back-up lights do not function.
23-1-3	Any exhaust leak can be felt with the bare hand six (6) inches from the leak in any direction (with the engine idling and the system unrestricted).

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.