

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Semi-Annual **Date:** 11/8/2018 **Time:** 8:48 AM
Name of School Corporation: BLUE RIVER SERVICES **Corp ID:** 450001
Address of School Corporation: 3141 Progress Blvd.
City: Corydon **Zip:** 47112 **County Number:** 31
VIN: 1GBJG31U961186373 **License Number:** 21079 **Bus Number:** 100
Make of Body: Chevrolet **Year:** 2006 **Make of Chassis:** Chevrolet **Year:** 2006
Bus Type: A2 **Mileage:** 207881
Inspection Status: O **Inspected By:** Troy Boyd **PE:** 5171

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
13-1-1	Any clearance light is missing, cracked, faded, wrong color, or inoperative
57-1-5	Step-well light is missing or inoperative

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
20-2-1	Is no audible signal when the emergency door is open and ignition switch is on
70-2-4	Audible warning device, when required, is not working properly. Buzzers are required after 5-2-94

Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.
2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.