

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Post-Crash Inspection	Date:	11/9/2018	Time:	9:22 AM
Name of School Corporation:	TIPTON COMMUNITY SCHOOL CORP.	Corp ID:	807945		
Address of School Corporation:	1051 S. Main St.				
City:	Tipton	Zip:	46072	County Number:	80
VIN:	1T7YT4E28D1157449	License Number:	4582	Bus Number:	22
Make of Body:	Thomas Built Buses, Inc.	Year:	2012	Make of Chassis:	Freightliner
Bus Type:	D	Mileage:	41137	Year:	2013
Inspection Status:	O	Inspected By:	Randy McPike	PE:	7018

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
4-1-2	See Notes: Any defect inspector deems a violation not listed
67-1-2	Rims are bent or loose
53-1-4	See Notes: Any defect inspector deems a violation not listed

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).
63-2-3	Any tire is flat

Bus Type Description

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.