REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Post-Crash Inspection		**Date:** 11/9/2018	**Time:**	9:22 AM
Name of School Corporation:	TIPTON COMMUNITY SCHOOL CORP.			**Corp ID:**	807945
Address of School Corporation:	1051 S. Main St.				
City:	Tipton	**Zip:**	46072	**County Number:**	80
VIN:	1T7YT4E28D1157449		**License Number:** 4582	**Bus Number:**	22
Make of Body:	Thomas Built Buses, Inc.	**Year:** 2012	**Make of Chassis:** Freightliner	**Year:**	2013
Bus Type:	D		**Mileage:** 41137		
Inspection Status:	O	**Inspected By:**	Randy McPike	**PE:**	7018

Violations - Rejected

Inspection Code	Description
4-1-2	See Notes: Any defect inspector deems a violation not listed
67-1-2	Rims are bent or loose
53-1-4	See Notes: Any defect inspector deems a violation not listed

Violations - Out of Service

Inspection Code	Description
24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).
63-2-3	Any tire is flat

Bus Type Description

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.