

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual	Date:	11/13/2018	Time:	9:49 AM		
Name of School Corporation:	OAK HILL UNITED SCHOOL CORP.	Corp ID:	525625				
Address of School Corporation:	PO Box 550						
City:	Converse	Zip:	46919	County Number:	52		
VIN:	4DRBUAFN08B493714	License Number:	30640	Bus Number:	12		
Make of Body:	IC Corporation	Year:	2007	Make of Chassis:	IC Corporation	Year:	2008
Bus Type:	C	Mileage:	115002				
Inspection Status:	R	Inspected By:	Randy McPike	PE:	7018		

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
23-1-5	Any hanger, clamp or bracket is missing, loose or broken
46-1-5	Upholstery or padding is ripped, torn, or improperly repaired

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
------------------------	--------------------

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.