

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b>	Semi-Annual	<b>Date:</b>	11/27/2018	<b>Time:</b>	1:14 PM
<b>Name of School Corporation:</b>	LINCOLN HILLS DEV. CENTER	<b>Corp ID:</b>	62002Z		
<b>Address of School Corporation:</b>	302 Main St				
<b>City:</b>	Tell City	<b>Zip:</b>	47586	<b>County Number:</b>	62
<b>VIN:</b>	1GBHG31V151242103	<b>License Number:</b>	21353	<b>Bus Number:</b>	21
<b>Make of Body:</b>	U.S. Bus Corporation	<b>Year:</b>	2005	<b>Make of Chassis:</b>	Chevrolet
<b>Bus Type:</b>	A2	<b>Year:</b>	2006		
<b>Inspection Status:</b>	R	<b>Inspected By:</b>	Kelly Hammond	<b>Mileage:</b>	70858
				<b>PE:</b>	6682

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
23-1-3	Any exhaust leak can be felt with the bare hand six (6) inches from the leak in any direction (with the engine idling and the system unrestricted).
62-1-2	One (1) taillight or one (1) brake light does not function
8-1-4	See Notes: Any defect inspector deems a violation not listed

### Violations - Out of Service

Inspection Code Description

### Bus Type Description

**Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:**

1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.
2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.