## REPORT OF SCHOOL BUS INSPECTION

Type of 9:45 Semi-Annual 11/29/2018 Time: Date: Inspection: AM LAPORTE COMMUNITY SCHOOL CORP.

Name of School Corporation:

464945 Corp ID:

**Address of School Corporation:** 1921 A St

County City: La Porte Zip: 46350 46 Number:

License VIN: 4UZABRDC17CX15459 21664 **Bus Number:** 59 Number:

Make of Thomas Built Buses, Year: 2006 Freightliner Year: Make of Body: 2007 Inc. Chassis:

**Bus Type:** С Mileage: 105781

Inspected PE: 7029 **Inspection Status:** O Nathan Sherer By:

## Violations - Rejected

**Inspection Code Description** 

35-1-1 A heater motor is not operating properly

## **Violations - Out of Service**

Inspection **Description** Code

Any brake line or hose is abraded (chafed), cracked, bulging or leaking (leaking at 7-2-4

other than a proper connection).

## **Bus Type Description**

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.