

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Semi-Annual **Date:** 12/4/2018 **Time:** 8:59 AM
Name of School Corporation: BETHESDA BAPTIST CHURCH & SCHOOL **Corp ID:** 323318
Address of School Corporation: 7950 N CR 650 E
City: BROWNSBURG **Zip:** 46112 **County Number:** 32
VIN: 1GDL7T1E82J509458 **License Number:** B891A **Bus Number:** 1
Make of Body: GMC **Year:** 2002 **Make of Chassis:** GMC **Year:** 2002
Bus Type: C **Mileage:** 111063
Inspection Status: O **Inspected By:** John Pang **PE:** 6196

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
2-1-1	Required back-up lights do not function.
46-1-5	Upholstery or padding is ripped, torn, or improperly repaired

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
8-2-1	There is no brake certification, or the certification has expired or is not signed

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.