

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Semi-Annual **Date:** 12/5/2018 **Time:** 8:36 AM
Name of School Corporation: WASHINGTON CATHOLIC SCHOOLS **Corp ID:** 14A664
Address of School Corporation: 201 N.E. 2nd St
City: Washington **Zip:** 47501 **County Number:** 14
VIN: 1GBJG31U961150747 **License Number:** B929AD **Bus Number:** 21
Make of Body: Mid Bus, Inc. **Year:** 2005 **Make of Chassis:** Chevrolet **Year:** 2006
Bus Type: **Mileage:** 82126
Inspection Status: R **Inspected By:** Kelly Hammond **PE:** 6682

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
23-1-3	Any exhaust leak can be felt with the bare hand six (6) inches from the leak in any direction (with the engine idling and the system unrestricted).
13-1-1	Any clearance light is missing, cracked, faded, wrong color, or inoperative

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
------------------------	--------------------

<u>Bus Type</u>	<u>Description</u>
-----------------	--------------------