

REPORT OF SCHOOL BUS INSPECTION

| | | | | | | | |
|---------------------------------------|------------------------------|------------------------|---------------|-------------------------|-----------|--------------|------|
| Type of Inspection: | Semi-Annual | Date: | 12/11/2018 | Time: | 10:40 AM | | |
| Name of School Corporation: | ST JOHN LUTHERAN SCHOOL (57) | | | Corp ID: | 220024 | | |
| Address of School Corporation: | 301 S Oak Street | | | | | | |
| City: | Kendallville | Zip: | 46755 | County Number: | 57 | | |
| VIN: | 1GBHG31V541195656 | License Number: | B826A | Bus Number: | 1 | | |
| Make of Body: | Collins Bus Corporation | Year: | 2004 | Make of Chassis: | Chevrolet | Year: | 2004 |
| Bus Type: | A1 | Mileage: | 53297 | | | | |
| Inspection Status: | O | Inspected By: | Wes Rowlander | PE: | 7427 | | |

Violations - Rejected

| <u>Inspection Code</u> | <u>Description</u> |
|------------------------|--|
| 68-1-1 | Washers do not function properly in any manner |

Violations - Out of Service

| <u>Inspection Code</u> | <u>Description</u> |
|------------------------|--|
| 8-2-1 | There is no brake certification, or the certification has expired or is not signed |

Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

- 1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.**
- 2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.**