REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Semi-Annual	**Date:**	12/11/2018	**Time:**	9:29 AM
Name of School Corporation:	EAST GIBSON SCHOOL CORPORATION			**Corp ID:**	262725
Address of School Corporation:	941 S Franklin St				
City:	Oakland City	**Zip:**	47660	**County Number:**	26
VIN:	4UZAAXCT24CM89484	**License Number:**	B137L	**Bus Number:**	11
Make of Body:	Freightliner **Year:** 2003	**Make of Chassis:**	Freightliner	**Year:**	2004
Bus Type:	C	**Mileage:**	103854		
Inspection Status:	R	**Inspected By:**	Bradley MIller	**PE:**	7809

Violations - Rejected

Inspection Code	Description
22-1-1	A dripping oil or fluid leak
70-1-10	If the emergency window instructions are illegible or missing. Must be within 6 inches of the release handle

Violations - Out of Service

Inspection Code	Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.