REPORT OF SCHOOL BUS INSPECTION

Type of 2:02 Time: Re-Inspection Date: 12/13/2018 Inspection: PM NETTLE CREEK SCHOOL CORP. Name of School Corporation: Corp ID: 898305 **Address of School Corporation:** 795 Baker Rd County City: Hagerstown Zip: 47346 89 Number: License VIN: 1BAKGCPH8BF278740 165 Bus Number: Number: Make of Blue Bird Blue Bird Year: 2010 Make of Body: Year: 2011 Corporation Chassis: Corporation **Bus Type:** С Mileage: 79129 Inspection Inspected О PE: Jeremy Mason 8139 Status: By:

Violations - Rejected

| Inspection Code | <u>Description</u> |
|-----------------|---------------------------------------------------------------|
| 34-1-1 | Any headlight is inoperative |
| 41-1-4 | There is debris in the bus. (needs cleaned/includes dirt) |
| 46-1-5 | Upholstery or padding is ripped, torn, or improperly repaired |

Violations - Out of Service

| Inspection Code | <u>Description</u> |
|-----------------|------------------------------------------------------------------------|
| 25-2-2 | Reflective glass is cracked, broken, or missing |
| 25-2-1 | Mountings are broken or bent badly enough to inhibit proper adjustment |

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.