

## REPORT OF SCHOOL BUS INSPECTION

**Type of Inspection:** Post-Crash Inspection      **Date:** 12/18/2018      **Time:** 9:53 AM  
**Name of School Corporation:** ELWOOD COMMUNITY SCHOOL CORP.      **Corp ID:** 485280  
**Address of School Corporation:** 1306 N Anderson St  
**City:** Elwood      **Zip:** 46036      **County Number:** 48  
**VIN:** 4DRBUSKP4AB185352      **License Number:** 33041      **Bus Number:** 4  
**Make of Body:** IC Corporation      **Year:** 2003      **Make of Chassis:** IC Corporation      **Year:** 2009  
**Bus Type:** B      **Mileage:** 91306  
**Inspection Status:** A      **Inspected By:** Jeremy Mason      **PE:** 8139

### Violations - Rejected

Inspection Code Description

### Violations - Out of Service

Inspection Code Description

### Bus Type Description

**Type B School Bus - A conversion or body constructed and installed upon a van or front-section vehicle chassis or stripped chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. Part of the engine is beneath and/or behind the windshield and beside the driver's seat. The entrance door is behind the front wheels.**