

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Post-Crash Inspection	Date:	12/26/2018	Time:	11:45 AM
Name of School Corporation:	VIGO COUNTY SCHOOL CORPORATION	Corp ID:	848030		
Address of School Corporation:	3250 Maple Ave				
City:	Terre Haute	Zip:	47804	County Number:	84
VIN:	4DRBWAAR6HB691220	License Number:	12467	Bus Number:	1624
Make of Body:	IC Corporation	Year:	2016	Make of Chassis:	IC Corporation
Year:	2017	Mileage:	24267	PE:	7008
Bus Type:	D	Inspected By:	Byron Goodman		
Inspection Status:	O				

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
11-1-2	The front or rear bumper is not properly attached, missing, torn, loose, or altered.
64-1-5	LED type lights have 25% to 49% of the pixels inoperable in any one light
64-1-4	Any front turn signal does not function properly
64-1-2	A lens is cracked, missing or wrong color
82-1-2	See Notes: Any defect inspector deems a violation not listed
34-1-1	Any headlight is inoperative
24-1-2	The bus body has loose, damaged or improperly aligned body parts. These would include rivets, bolts, and body panels and/or rub rails

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
24-2-2	Any body surface protrudes beyond the normal limits of the body structure
24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).

Bus Type Description

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.