

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Post-Crash Inspection	Date:	1/9/2019	Time:	10:20 AM
Name of School Corporation:	CENTERVILLE-ABINGTON COMM SCHS	Corp ID:	898360		
Address of School Corporation:	116 W SOUTH ST				
City:	CENTERVILLE	Zip:	47330	County Number:	89
VIN:	4UZABRDT99CAJ4786	License Number:	32100	Bus Number:	26
Make of Body:	Thomas Built Buses, Inc.	Year:	2009	Make of Chassis:	Freightliner
Bus Type:	C	Year:	2008		
Inspection Status:	O	Mileage:	91807	Inspected By:	Jeremy Mason
		PE:	8139		

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
11-1-2	The front or rear bumper is not properly attached, missing, torn, loose, or altered.

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
70-2-1	Any glass or glazing is broken through or missing

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.