

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b> Annual	<b>Date:</b> 1/16/2019	<b>Time:</b> 9:07 AM
<b>Name of School Corporation:</b> GREENSBURG COMMUNITY SCHOOLS	<b>Corp ID:</b> 161730	
<b>Address of School Corporation:</b> 1312 W Westridge Parkway		
<b>City:</b> Greensburg	<b>Zip:</b> 47240	<b>County Number:</b> 16
<b>VIN:</b> 4DRBWAAR5BB334330	<b>License Number:</b> 75119	<b>Bus Number:</b> 16
<b>Make of Body:</b> IC Corporation	<b>Year:</b> 2010	<b>Make of Chassis:</b> IC Corporation
<b>Year:</b> 2011	<b>Mileage:</b> 59051	<b>PE:</b> 6665
<b>Bus Type:</b> D	<b>Inspected By:</b> Chris Clark	
<b>Inspection Status:</b> O		

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
20-1-8	If bus manufactured after 5-2-1994, positive door opening device is missing or fails to operate properly

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
20-2-1	Is no audible signal when the emergency door is open and ignition switch is on

### Bus Type Description

**Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.**