REPORT OF SCHOOL BUS INSPECTION

| Type of Inspection: | Annual | | | Date: | 1/23/2019 | Time: | 9:27 AM |
|--------------------------------|----------------------------|-------|----------------------------|---------------------|-----------|-------------------|------------|
| Name of School Corporation: RI | | RISIN | SING-SUN OHIO COUNTY COMM. | | | Corp ID: | 586080 |
| Address of School Corporation: | | | 110 Henrietta St | | | | |
| City: | Rising Sun | | Zip: | 47040 | | County Number: | 58 |
| VIN: | 1GB3G2BG8B117468 | 7 | | License Number: | 6198 | Bus Number: | A1 |
| Make of Body: | Collins Bus Corporation | Year: | : 2011 | Make of Chassis: | Chevrolet | Year: | 2011 |
| Bus Type: | | | | Mileage: | 52736 | | |
| Inspection Status | : R | | Inspected By: | Chris Clark | | PE: | 6665 |

Violations - Rejected

| Inspection Code | Description |
|--------------------|--|
| 23-1-2 | Any component has deteriorated and allows the escape of exhaust gases (with the engine idling and the system unrestricted) |

Violations - Out of Service

Inspection Code Description

Bus Type Description