REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Semi-Annual			**Date:**	1/28/2019	**Time:**	12:38 PM
Name of School Corporation:		CLOVERDALE COMMUNITY SCHOOLS				**Corp ID:**	676750
Address of School Corporation:		310 E Logan St					
City:	Cloverdale	**Zip:**	46120			**County Number:**	67
VIN:	1T7YT4A2181297984			**License Number:**	16080	**Bus Number:**	21
Make of Body:	Thomas Built Buses, Inc.	**Year:**	2007	**Make of Chassis:**	Thomas Built Buses, Inc.	**Year:**	2008
Bus Type:	D			**Mileage:**	70609		
Inspection Status:	R	**Inspected By:**	Byron Goodman			**PE:**	7008

Violations - Rejected

Inspection Code	Description
65-1-1	Any lens is cracked, broken or discolored

Violations - Out of Service

Inspection Code	Description

Bus Type Description

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.